| Product: | FETK-T1.0A | Rev : | 21 | Page 1 of 15 |
|----------|---------------|-------|----|--------------|
| Title : | Release-Notes | | | |

ETAS

DRIVING EMBEDDED EXCELLENCE

| Product : | FETK-T1.0A | FETK-T1.0A | | | |
|------------|--|----------------------|-----------------------|-----------------|--|
| Title : | Release Notes | | | | |
| File : | FETK-T1.0A_Release-N | lotes_V21.docx | | | |
| TTNR: | F-00K-109-977 | F-00K-109-977 | | | |
| Comments : | Currently shipped: 11111637B011/01 FPGA-Boot version: V1.1.1 FPGA-A version: V1.16.37 Hardware-state: B011/01 | | | | |
| Created: | Name Department Signature Date R. Mai PGA/PRM-M R. Mai 2021-03-10 | | | | |
| Released: | Name A. Sprenger | Department EAL-AR | Signature A. Sprenger | Date 2021-03-10 | |

$C\,h\,a\,n\,g\,e\,s$

| Revision | Description | Date | Name | Signature |
|----------|---|------------|------|-----------|
| 01 | 102103B010/01 - for FETK-T1.0A - Initial version | 2016-03-18 | Mai | Mai |
| 02 | 102104B011/01 - SBB V2.1 support added and Heat Spreader exchanged | 2016-04-12 | Mai | Mai |
| 03 | 102105B011/01 - FPGA Update for MCE V2 and SW debugger arbitration | 2016-06-08 | Mai | Mai |
| 04 | 102107B011/01 - FPGA Update for several Features and Bug fixes [chapter 3.1 and 5.3] | 2016-09-14 | Mai | Mai |
| 05 | 102108B011/01 - FPGA Update for several Features and Bug fixes [chapter 3.1] and 5.3] | 2016-10-17 | Mai | Mai |
| 06 | 1021011B011/01 - FPGA Update for Bug fix [chapter <u>3.1</u> and <u>5.3</u>] | 2016-11-23 | Spr | Spr |
| 07 | 102111B011/01 - FPGA Update for Bug fix [chapter <u>3.1</u> and <u>5.3</u>] | 2016-12-02 | Spr | Spr |
| 08 | 102137B011/01 - FPGA Update for DAP2 and Bug fix [chapter 3.1 and 5.3] | 2017-05-08 | Mai | Mai |

| Product: | FETK-T1.0A | Rev : | 21 | Page 2 of 15 |
|----------|---------------|-------|----|--------------|
| Title : | Release-Notes | | | |

ETAS

DRIVING EMBEDDED EXCELLENCE

| 09 | 111146B011/01 - FPGA Update for monitor variables and bug fix [chapter 3.1 and 5.3] | 2017-09-11 | Spr | Spr |
|----|---|------------|----------|----------|
| 10 | 111155B011/01 - FPGA Update for monitor variables and bug fix [chapter 3.1] | 2017-11-20 | Mai | Mai |
| 11 | 1111610B011/01 - FPGA Update for monitor variables and bug fix [chapter 3.1 and 5.3] | 2018-01-30 | Mai | Mai |
| 12 | 1111733B011/01 - FPGA Update [chapter <u>3.1</u> and <u>5.3</u>] | 2018-06-22 | Mai | Mai |
| 13 | 1111824B011/01 - FPGA Update for bug fix [chapter <u>3.1</u> and <u>5.3</u>] | 2018-09-17 | Mai | Mai |
| 14 | 1111934B011/01 - FPGA Update and bug fix [chapter <u>3.1</u> and <u>5.3</u>] | 2018-11-21 | Mai | Mai |
| 15 | 11111017B011/01 - FPGA Update and bug fix [chapter <u>3.1</u> and <u>5.3</u>] | 2019-03-05 | Mai | Mai |
| 16 | 11111017B011/01 - New or Enhanced Functions [3.1] | 2019-05-29 | Mai | Mai |
| 17 | 11111017B011/01 - New or Enhanced Functions [3.1] | 2019-09-05 | Mai | Mai |
| 18 | 11111026B011/01 - New or Enhanced Functions [3.1] | 2019-09-05 | Sprenger | Sprenger |
| 19 | 11111310A010/01 - New or Enhanced Functions $[\underline{3.1}]$ and Firmware Modification $[\underline{5.3}]$ | 2020-06-10 | Mai | Mai |
| 20 | 11111419A010/01 - New or Enhanced Functions $[\underline{3.1}]$ and Firmware Modification $[\underline{5.3}]$ | 2020-09-17 | Mai | Mai |
| 21 | 11111637A010/01 - New or Enhanced Functions $[\underline{3.1}]$ and Firmware Modification $[\underline{5.3}]$ | 2021-03-10 | Mai | Mai |

ET/S

Title : Release-Notes

FETK-T1.0A

Rev:

21

Product:

Table of content

| 1 | General Information | |
|--------|--|---|
| 1.1 | Safety Notice | |
| 1.2 | System Requirements | |
| 1.3 | Restrictions | 5 |
| 1.4 | Miscellaneous | 6 |
| 2 | Version Syntax and Tool-Chain Information | 6 |
| 2.1 | Version-Syntax of the FETK-T1.0A | 6 |
| 2.2 | Version information of the tool-chain components | 7 |
| 2.3 | Hardware support | 7 |
| 2.4 | Software and microcontroller support | 7 |
| 3 | What's New - Release Notes | 8 |
| 3.1 | New or Enhanced Functions | 8 |
| 3.1.1 | In INCA 7.3.4 and HSP V12.4.0 | 8 |
| 3.1.2 | In INCA 7.3.2 and HSP V12.2.0 | 8 |
| 3.1.3 | In INCA 7.3.1 and HSP V12.1.0 | 8 |
| 3.1.4 | In INCA 7.2.15 and HSP V11.15.2 | 8 |
| 3.1.5 | In INCA 7.2.14 and HSP V11.14.0 | |
| 3.1.6 | In INCA 7.2.13 and HSP V11.13.0 | |
| 3.1.7 | In INCA 7.2.12 and HSP V11.12.0 | |
| 3.1.8 | In INCA 7.2.11 and HSP V11.11.0 | |
| 3.1.9 | In INCA 7.2.10 and HSP V11.10.0 | |
| 3.1.10 | In INCA 7.2.7 and HSP V11.7.0 | |
| 3.1.11 | In INCA 7.2.7 and HSP V11.7.0 | |
| 3.1.12 | In INCA 7.2.6 and HSP V11.6.0 | |
| 3.1.13 | In INCA 7.2.5 and HSP V11.5.0 | |
| 3.1.14 | In INCA 7.2.4 and HSP V11.4.0 | |
| 3.1.15 | In INCA 7.2.3 and HSP V11.3.1 | |
| 3.1.16 | In INCA 7.2.3 and HSP V11.3.0 | |
| 3.1.17 | In INCA 7.2.2 HF2 and HSP V11.2.3 | |
| 3.1.18 | In INCA 7.2.2 HF2 and HSP V11.2.1 | |
| 3.1.19 | In INCA 7.2.2 and HSP V11.2.0 | |
| 3.1.20 | In INCA 7.2.1 and HSP V11.1.0 | |
| 3.1.21 | In INCA 7.2.0 and HSP V11.0.1 | |
| 3.1.22 | In INCA 7.2.0 and HSP V11.0.0 | |
| 3.2 | Known issues | |
| 3.2.1 | In INCA 7.2.7 and HSP V11.7.0 | |
| 3.2.2 | In HSP V11.3.0 | |
| 3.2.3 | In INCA 7.2.3 and HSP V11.3.0 | |
| 3.2.4 | In INCA 7.2.2 HF2 and HSP V11.2.3 | |
| 3.2.5 | In INCA 7.2.0 and HSP V11.0.0 | |
| 4 | Product Variants | |
| 4.1 | FETK-T1.0A. | |
| 5 | Firmware Modifications | |
| 5.1 | General remarks to this chapter | |
| 5.2 | FPGA-Boot-Code | |
| 5.3 | FPGA-Code | |
| 6 | Hardware Modifications | |
| 6.1 | General remarks to this chapter | |
| 6.2 | Details of Change | |
| J | | |

| Product: | FETK-T1.0A | Rev: | 21 | Page 4 of 15 |
|----------|---------------|------|----|--------------|
| Title : | Release-Notes | | | |

| 6.2.1 | Change from hardware state B010 to hardware state B011 | . 16 |
|-------|--|------|
| 6.3 | Hardware delivery condition | . 16 |
| | Abbreviations | |

| Product: | FETK-T1.0A | Rev : | 21 | Page 5 of 15 |
|----------|---------------|-------|----|--------------|
| Title : | Release-Notes | | | |



1 General Information

1.1 Safety Notice

Calibration activities influence the behavior of the ECU and the systems controlled by the ECU. This may result in unexpected behavior of the vehicle and thus can lead to safety critical situations. Only well trained personnel should be allowed to perform calibration activities.

1.2 System Requirements

The following minimum system prerequisites have to be met:

Required Hardware

- GHz Processor
- GB RAM
- DVD-ROM drive (for installation)
- Network adapter
- Graphics with a resolution of at least 1024x768, 256 MB RAM, 16bit color and DirectX9

Required Operating System

- Windows® 7 SP1 (32 or 64bit*) or higher.
- Windows® 8 (32 / 64 bit*) and Windows® 8.1 (32 / 64 bit*)
- Windows® 10
- *) INCA uses the 32bit compatibility mode on a 64-bit operating system.

Required Free Disk Space

 1 GB (not including the size for user data; absolute min. required, but not recommended)

The following system prerequisites are recommended:

Recommended Hardware

- GHz Quad-Core Processor or equivalent
- 16 GB RAM
- DVD-ROM drive (for installation)
- Network adapter
- Graphics with a resolution of at least 1280 x 1024, 1GB RAM, 32bit color and DirectX9 Recommended Operating System
 - Windows® 7 SP1 64bit (INCA uses the 32bit compatibility mode on a 64-bit operating system)

Recommended Free Disk Space

• >10 GB

Recommendation on Performance

- Investigation on performance showed:
 - o More Memory improves execution time of repetitive operations
 - SSD hard disks improve the file access times

1.3 Restrictions

WINDOWS® 95b, WINDOWS® NT, WINDOWS® 2000, WINDOWS® 98SE, and WINDOWS® XP are not supported

| Product: | FETK-T1.0A | Rev: | 21 | Page 6 of 15 |
|----------|---------------|------|----|--------------|
| Title : | Release-Notes | | | |



1.4 Miscellaneous

To ensure the highest data throughput from the FETK device up to the PC system the following recommendations should be considered:

- Set power save mode to the highest level
- Disable virus scan
- Use network adapter for ETAS application only
- Update network adapter drivers

2 Version Syntax and Tool-Chain Information

2.1 Version-Syntax of the FETK-T1.0A

The **FETK-T1.0A hardware version** information is located on the product sticker and can be read out of the FETK using the firmware update tool HSP or XETK Configuration Tool.

Overall Hardware Version Syntax: aaabbbcddd/ee

Description of PLD-Code Information (modification details refer chapter 3)

aaa FPGA-Boot-Code version (1.0.0, 1.0.1, 1.0.2, ...) **bbb** FPGA-Code version (1.0.0, 1.0.1, 1.0.2, ...)

The hardware version of the PCB is also located on the label attached to the PCBs. These version is subordinate to the Overall hardware state cannot be read out by software.

PCB Hardware State Syntax: deee/ff

Description of Hardware-Information (modification details refer chapter 4)

c PCB Version (A=V1.0, B=V1.1, C=V1.2, ...)
ddd PCB Hardware State (010, 011, 012, ...)
ee PCB Population Variant (00, 01, 02, ...)

The first delivered hardware state of the FETK-T1.0A is the following:

FETK-T1.0A: **102103B010/01**

| Product: | FETK-T1.0A | Rev : | 21 | Page 7 of 15 |
|----------|---------------|-------|----|--------------|
| Title : | Release-Notes | | | |

2.2 Version information of the tool-chain components

To get this FETK running with the other components of the tool-chain please make sure that the version mentioned below or a newer one is used. If your software, firmware or hardware version is older, please update it.

If you have any problems to get this FETK running please contact our local customer support or sales representative.

Updates or refreshes can be downloaded from the ETAS homepage:

http://de.etasgroup.com

http://en.etasgroup.com

2.3 Hardware support

The FETK-T1.0A is supported by ES891.

2.4 Software and microcontroller support

| Microcontroller | HSP | INCA | ETK Tools | ASCET-RP | INTECRIO |
|--------------------|---------|--------|------------------|----------|----------|
| | | | - | - | - |
| TC27x-ED C-Step 1) | V11.0.0 | V7.2.0 | V4.1.0 | V6.4.1 | V4.6.1 |
| TC29x-ED | V11.0.0 | V7.2.0 | V4.1.0 | V6.4.1 | V4.6.1 |

¹⁾ and higher versions (microcontroller steps) if they support the C-step specifications

| Product: | FETK-T1.0A | Rev: | 21 | Page 8 of 15 |
|----------|---------------|------|----|--------------|
| Title : | Release-Notes | | | |



3 What's New - Release Notes

This chapter lists the main improvements compared to a previous shipped FETK product. Additionally, a detailed list of already known issues can be found here.

3.1 New or Enhanced Functions

3.1.1 In INCA 7.3.4 and HSP V12.4.0

| Issue Identifier | Description |
|------------------|--|
| ETKF-1264 | MAXWAIT - implement chosen solution |
| ETKF-1289 | Disallow illegal DAP settings in hwcfg.lua (160MHz + 2-Pin-DAP |

3.1.2In INCA 7.3.2 and HSP V12.2.0

| Issue Identifier | Description |
|----------------------|--|
| ETKF-1206; 627542 | Support CPLD Update for all FETK-T1.x |
| ETKF-1027 | Implement Concurrent XCP debugging and flashing for FETK-T1.1B |
| ETKF-1187 | Performance Improvement overflows/bottlenecks for all FETK-T1.x |
| ETKF-1025; 623845 | TEA MGR - Implementation of Handling host port disconnections in stacked ES8xx for all FETK-T1.x |
| ETKF-1016 | Improve startup behavior of DAP for all FETK-T1.x |

3.1.3 In INCA 7.3.1 and HSP V12.1.0

| Issue Identifier | Description |
|------------------|---|
| ETKF-1104 | Prevent issues when switching between DAP modes |
| ETKF-1022 | Added monitor variables for EDE ingress profiling |
| ETKF-1064 | Increased data size of Trace-FIFO to 4 KByte |

3.1.4 In INCA 7.2.15 and HSP V11.15.2

| Issue Identifier | Description |
|------------------|--------------------------------------|
| 627542 | ECU reset with FETK in Sleep Mode |
| 630645 | ECU reset after FETK in Deep Standby |

3.1.5 In INCA 7.2.14 and HSP V11.14.0

| Issue Identifier | Description |
|------------------|-----------------------------------|
| ETKPRG-387 | Support of standard XCP debugging |

3.1.6 In INCA 7.2.13 and HSP V11.13.0

| Tarana TalanakiCan | D. a. a. disabilita sa |
|--------------------|------------------------|
| Issue Identifier | Description |
| | |

| Product: | FETK-T1.0A | Rev : | 21 | Page 9 of 15 |
|----------|---------------|-------|----|--------------|
| Title : | Release-Notes | | | |



| n/a | Support of XCP Time Correlation |
|--------|---------------------------------|
| l II/a | Support of ACF Time Correlation |

3.1.7 In INCA 7.2.12 and HSP V11.12.0

| Issue Identifier | Description |
|------------------|----------------------------|
| 603293 | Higher current consumption |
| 604175 | High jitter of DAQ packets |

3.1.8 In INCA 7.2.11 and HSP V11.11.0

| Issue Identifier | Description |
|------------------|---|
| n/a | Support of FETK Alias name |
| n/a | Improve round trip time for FETK in combination |
| | with ES830 (Rapid prototyping) |
| 601278 | FETK-T1 reports Aurora link error and repeats |
| | AGBT initialization after ECU reset |
| 603463 | FETK sporadically generates wrong measurement |
| | values for trace raster |

3.1.9 In INCA 7.2.10 and HSP V11.10.0

| Issue Identifier | Description |
|------------------|--|
| 585919 | 3 pin DAP setting is inconsitent for FETK-T1.0A |
| 593091 | Access to ED RAM could fail while concurrently using a debugger by debug api |

3.1.10 In INCA 7.2.7 and HSP V11.7.0

| Issue Identifier | Description | | |
|------------------|--|--|--|
| 581275 | Bugfix: FETK-T1.0 XCP Connection interruption in | | |
| | climate test during trace mirror collision test | | |

3.1.11 In INCA 7.2.7 and HSP V11.7.0

| Issue Identifier | Description |
|------------------|---|
| 578494 | Bugfix: FETK ECU Access error when debugger is connected |
| n/a | support of Fine Grained Trace Windows (Infineon Errata MCDS_TC.059 to be considered for TC2xx ECU Software) |

3.1.12 In INCA 7.2.6 and HSP V11.6.0

| Issue Identifier | Description |
|------------------|--|
| n/a | Added monitoring variable for Trace Mirror Valid |

| Product: | FETK-T1.0A | Rev: | 21 | Page 10 of 15 |
|----------|---------------|------|----|---------------|
| Title : | Release-Notes | | | |



| n/a | Extended the XCP debug commands DBG_HWIO_AVAILABLE and DBG_HWIO_SET_GET in order to support to monitor the target power supply and the WDGDIS pin |
|--------|---|
| 572086 | bug fix for debug arbitration with Lauterbach Trace32 |
| 578016 | FETK-T1.0 asserts ECUPOR when going into sleep mode |
| 576178 | FETK, XCP debugging: Behavior of WDGDIS pin does not match with HW arbitration |

3.1.13 In INCA 7.2.5 and HSP V11.5.0

| Issue Identifier | Description |
|------------------|---|
| n/a | Support of DAP2 (3-Pin) with max 100Mhz |
| 562626 | Overflows are always handles as fatal errors |
| 562628 | No HSP update it possible if lots of EV_DAQ_OVERLOAD events occur |

3.1.14In INCA 7.2.4 and HSP V11.4.0

| Issue Identifier | Description | |
|------------------|---|--|
| 560302 | Improved management of non-recoverable trace errors | |
| | | |

3.1.15 In INCA 7.2.3 and HSP V11.3.1

| Issue Identifier | Description |
|------------------|---|
| 551165 | Measure with FETK-T results in incorrect measured values (64bit values) |
| 557638 | Measurement Data Overflow with FETK-T |
| n/a | Added firmware monitoring variables |

3.1.16In INCA 7.2.3 and HSP V11.3.0

| Issue Identifier | Description | | |
|------------------|--|--|--|
| n/a | Trace measurement improvement | | |
| n/a | Support of reconfigurable size, moveable EMU RAM (LERT V3) | | |
| n/a | XCP Debug API: responsive behavior in case of non- | | |
| | existing memory access improved | | |
| n/a | Support of IEEE 1588 time synchronization | | |
| 553146, 551481 | Improved stability of FETK Update | | |

3.1.17 In INCA 7.2.2 HF2 and HSP V11.2.3

| Tarana Talanakifian | D |
|---------------------|-------------|
| Issue Identifier | Description |
| | |

| Product: | FETK-T1.0A | Rev : | 21 | Page 11 of 15 |
|----------|---------------|-------|----|---------------|
| Title : | Release-Notes | | | |

| 550301 | Invalid measurement data in case of unaligned | | |
|--------|---|--|--|
| | writing to 32 bit data | | |

3.1.18 In INCA 7.2.2 HF2 and HSP V11.2.1

| Issue Identifier | Description | | |
|------------------|--|--|--|
| n/a | increased performance for debugging over XCP | | |
| 502023 | Support of fast raster use cases | | |
| 534258 | Performance optimization of ETK on ES891. 100µs raster beside other raster is now possible | | |

3.1.19In INCA 7.2.2 and HSP V11.2.0

| Issue Identifier | Description | | | |
|------------------|---|--|--|--|
| n/a | Accerlate Trace Mirror initialization, decrease measurement gap in case of measurement overflow | | | |
| n/a | enhancement of monitor to log lost measurement data | | | |
| 523060 | Confusing WP checksum displayed in INCA after power cycle of ES891 | | | |
| 539446 | FETK-T stays in boot mode after HSP update from HSP11.0.1 to HSP11.1.0 | | | |

3.1.20In INCA 7.2.1 and HSP V11.1.0

| Issue Identifier | Description | | |
|------------------|--|--|--|
| n/a | FETK-T Start of Measurement Improvements | | |
| | (Configuration DISTAB and Trace Interface) | | |
| n/a | SW debugger arbitration for FETK (Debug API) | | |
| n/a | MCEv2.0 support for FETK-T1 | | |
| 520596 | RP_Wait and MC_Wait are not cleared when | | |
| | Ethernet connection to ES891 is lost | | |

3.1.21In INCA 7.2.0 and HSP V11.0.1

| Issue Identifier | Description | | |
|------------------|---|--|--|
| n/a | support of SBB V2.1 added | | |
| | (SBB V3.1 was already available with initial version) | | |

3.1.22 In INCA 7.2.0 and HSP V11.0.0

| Issue Identifier | Description | |
|------------------|--|--|
| n/a | Initial version, support of FETK-T1.0A | |

| Product: | FETK-T1.0A | Rev : | 21 | Page 12 of 15 |
|----------|---------------|-------|----|---------------|
| Title : | Release-Notes | | | |



3.2 Known issues

3.2.1 In INCA 7.2.7 and HSP V11.7.0

| Issue Identifier | Description | | |
|------------------|--|--|--|
| #581311 & | For Fine Grained Trace, Infineon Errata | | |
| #581332 | MCDS_TC.059 has to be considered for TC2xx ECU | | |
| | Software | | |

3.2.2 In HSP V11.3.0

| Issue Identifier | Description | | |
|------------------|---|--|--|
| # 566456 | Incompatibility between ES891 with HSP 11.3.0 and | | |
| | FETK-T with HSP 11.4.0 | | |

3.2.3 In INCA 7.2.3 and HSP V11.3.0

| Issue Identifier | Description | |
|------------------|---|--|
| # 551165 | Invalid measurement data in case of unaligned writing to 64 bit data. | |

3.2.4 In INCA 7.2.2 HF2 and HSP V11.2.3

| Issue Identifier | Description | |
|------------------|---|--|
| # 551165 | Invalid measurement data in case of unaligned | |
| | writing to 64 bit data. | |

3.2.5 In INCA 7.2.0 and HSP V11.0.0

| Issue Identifier | Description | | |
|------------------|--|--|--|
| # 518120 | Sporadically the handshake between ECU and FETK- T fails. Remedy is to acknowledge the reset in INCA dialog box. | | |

| Product: | FETK-T1.0A | Rev: | 21 | Page 13 of 15 |
|----------|---------------|------|----|---------------|
| Title : | Release-Notes | | | |



4 Product Variants

In general the FETK-T1.0A can be purchased in one variant.

4.1 FETK-T1.0A

| Item number | F-00K-109-977 | | | |
|------------------------------------|---|--|--|--|
| Description | FETK-T1.0A Emulator Probe for the Infineon AURIX | | | |
| | microprocessor family | | | |
| For details refer the datasheet | | | | |
| | | | | |
| | X K | | | |
| | | | | |
| | DIM MILLIMETERS INCHES | | | |
| | A 56.50 ^{+0.2} 2.224 ^{+0.008} | | | |
| | B 53.00±0.2 2.087±0.008 | | | |
| | C 43.70±82 1.720±8.008 | | | |
| | D 15.50±8.2 0.610±8.008 | | | |
| | E 20.90±0.2 0.823±0.008 | | | |
| | F 3.00 ⁺ 0.2 0.118 ^{+0.008} | | | |
| | G 3.50+0:1 0.138+0.004 | | | |
| | H 33.25 ⁺ 0.2 1.309 ⁺ 0.008 | | | |
| | I 30.00 ^{+0.2} 1.181 ^{+0.008} | | | |
| | J 9.00 ^{+0.2} 0.354 ^{+0.008} | | | |
| | K 12.00 ^{+0.2} 0.472 ^{+0.004} | | | |

| Product: | FETK-T1.0A | Rev : | 21 | Page 14 of 15 |
|----------|---------------|-------|----|---------------|
| Title : | Release-Notes | | | |



5 Firmware Modifications

5.1 General remarks to this chapter

The programmable logic code within the FETK-T1.0A is stored onto programmable logic devices (FPGA). For the version syntax please refer to chapter 2.1.

Attention:

For updating the FETK - firmware with a later version by using HSP, all FETK firmware packages will be updated one after another. This will last a few minutes and must not be cancelled by the user. In case the firmware update had been finished unsuccessfully due to some reason, the update will have to be repeated. HSP will program the rescue packages onto the FETK. This procedure makes the firmware update fail-safe.

5.2 FPGA-Boot-Code

| Revision | Description |
|---------------|---|
| Version 1.0.2 | Initial Version |
| Version 1.1.1 | FETK-T1.0 asserts ECUPOR when going into sleep mode (bug fix #578016) |

Delivery condition:

The FPGA-Boot version 1.1.1 will be programmed into all shipments

5.3 FPGA-Code

| Revision | Description | | |
|----------------|--|--|--|
| Version 1.0.3 | Initial Version | | |
| Version 1.0.4 | Service Based Bypass Version 2.1 support added (SBB V3.1 was already available with initial version) | | |
| Version 1.0.5 | Start of Measurement improvements, SW debugger arbitration and MCE V2 support added | | |
| Version 1.0.7 | File system update | | |
| Version 1.0.8 | - Support for fast raster use cases - Increased performance for debugging over XCP | | |
| Version 1.0.11 | Invalid measurement data in case of unaligned writing to 32 bit data | | |
| Version 1.1.1 | - Trace measurement improvement - Improved stability of FETK Update (#553146, 551481) | | |
| Version 1.2.3 | - Added firmware monitoring variables - Bug fixes (#551165, 557638) | | |
| Version 1.2.4 | - Bug fix (#560302) | | |
| Version 1.3.7 | - Added DAP2 (3-Pin) support with 100Mhz - Bug fixes (#562626, 562628) | | |
| Version 1.4.6 | - Added monitoring variable for Trace Mirror Valid | | |

| Product: | FETK-T1.0A | Rev : | 21 | Page 15 of 15 |
|----------|---------------|-------|----|---------------|
| Title : | Release-Notes | | | |

ETAS

DRIVING EMBEDDED EXCELLENCE

| | - Extended the XCP debug commands DBG_HWIO_AVAILABLE and |
|-----------------|---|
| | DBG_HWIO_SET_GET in order to support to monitor the target |
| | power supply and the WDGDIS pin |
| | - Bug fixes (#572086, 578016 and 576178) |
| Version 1.5.5 | Bug fix: |
| | - 578494 FETK ECU Access error when debugger is connected |
| Version 1.6.10 | Bugfix: FETK-T1.0 XCP Connection interruption in climate test during |
| | trace mirror collision test |
| Version 1.8.24 | Bugfix: |
| | - 585919: 3 pin DAP setting is inconsitent for FETK-T1.0A |
| | - 593091: Access to ED RAM could fail while concurrently using a |
| | debugger by debug api |
| Version 1.9.34 | - support of FETK Alias name |
| | - RP improvements for Roundtrip time with ES830 |
| | Bugfix: (601278 and 603463) |
| Version 1.10.17 | Bugfix: - 603293: Higher current consumption |
| | - 604175: High jitter of DAQ packets |
| Version 1.10.26 | Bugfix: - 627542: ECU reset with FETK in Sleep Mode |
| | - 630645 ECU reset after FETK in Deep Standby |
| Version 1.13.10 | Bugfix - ETKF-1104: Prevent issues when switching between DAP modes |
| | - ETKF-1022: Added monitor variables for EDE ingress profiling |
| | - ETKF-1064: Increased data size of Trace-FIFO to 4 Kbyte |
| Version 1.14.19 | Bugfix - ETKF-1206: Support CPLD Update FETK |
| | - ETKF-1016: Improve startup behavior of DAP |
| Version 1.16.37 | ETKF-1264: DapIncreasedMaxwait |
| | ETKF-1250: Optimize job format of TEA device ETKF-1289: Disallow illegal DAP settings in hwcfg.lua |
| | ETKF-1367: Improve error handling in hwcfg.lua plugins |
| | |

Delivery condition:

The FPGA version 1.16.37 will be programmed into all shipments

| Product: | FETK-T1.0A | Rev : | 21 | Page 16 of 15 |
|----------|---------------|-------|----|---------------|
| Title : | Release-Notes | | | |



6 Hardware Modifications

6.1 General remarks to this chapter

Hardware issues or obsolete parts can make it necessary to modify the population of the FETK. Information about the modifications is listed underneath. The hardware state starts with version **B010/01**. For the version syntax please refer to chapter 2.1.

6.2 Details of Change

6.2.1 Change from hardware state B010 to hardware state B011

| Issue Identifier | Description |
|------------------|---|
| n/a | Milled Head Spreader was exchanged by die cast Heat Spreader |

6.3 Hardware delivery condition

The hardware state **B011/01** will be delivered with all new shipments.

| Product: | FETK-T1.0A | Rev : | 21 | Page 17 of 15 |
|----------|---------------|-------|----|---------------|
| Title : | Release-Notes | | | |

7 Abbreviations

| ASCET-RP | Rapid Prototyping Software of ETAS |
|-------------------------|--|
| CPLD | Complex Programmable Logic Device |
| ES891 | MC hardware |
| FETK | Product (emulator test probe) |
| firmware | Software for MC hardware; necessary for implementation |
| | of new features or bug fixes |
| FPGA | Field Programmable Gate Array; interface component to |
| | the application hardware |
| Hot-fix | Software bug-fix for a refresh version |
| HS | Heat Spreader |
| HSP | Hardware Service Pack; ETAS product which includes the |
| | firmware for the complete ETAS hardware, shipped |
| | together with INCA but also available as standalone |
| | product, download at ETAS homepage possible |
| INCA | Measurement and Calibration Software of ETAS |
| INTECRIO | Rapid Prototyping Software of ETAS |
| MC | Measurement & Calibration |
| PCB | Printed Circuit Board |
| RP | Rapid Prototyping |
| SBB | Service Based Bypass |
| tool-chain | MC hardware (e.g. ES690) and software (e.g. INCA) |
| XETK Configuration Tool | Configuration Software, in order to configure a (X)ETK / |
| | FETK |