

RTA-OS Z20K-M4-GHS

Release Note - Version 2.0.0 (16-08-2022)



Copyright

The data in this document may not be altered or amended without special notification from ETAS GmbH. ETAS GmbH undertakes no further obligation in relation to this document. The software described in it can only be used if the customer is in possession of a general license agreement or single license. Using and copying is only allowed in concurrence with the specifications stipulated in the contract. Under no circumstances may any part of this document be copied, reproduced, transmitted, stored in a retrieval system or translated into another language without the express written permission of ETAS GmbH.

©Copyright 2008-2022 ETAS GmbH, Stuttgart.

The names and designations used in this document are trademarks or brands belonging to the respective owners.

Document: 10979-RN-2.0.0 EN-08-2022(16-08-2022)



Safety Notice

This ETAS product fulfills standard quality management requirements. If requirements of specific safety standards (e.g. IEC 61508, ISO 26262) need to be fulfilled, these requirements must be explicitly defined and ordered by the customer. Before use of the product, customer must verify the compliance with specific safety standards.



Contents

1	1.1 1.2	Version Information	
2	Open El	II Calls	6
3	Change 3.1 3.2	History Version 2.0.0 Version 1.99.0	7
4	Fixed El	II Calls	8
5	Limitati 5.1 5.2	ons Installer	
6	Contact 6.1 6.2	ing ETAS Technical Support	10 10



1 Introduction

RTA-OS is an AUTOSAR compliant Operating System and associated tooling. This document provides release information for the RTA-OS Z20K-M4-GHS port plug-in that customizes the RTA-OS development tools for the Zhixin Z20K14xM with the GreenHills compiler. It supplements the more general information you can find in the *Release Note*.

1.1 Version Information

This is Version 2.0.0 of the RTA-OS Z20K-M4-GHS plug-in.

1.2 Installation

The installation process is covered in detail in the Z20K-M4-GHS Port Guide.



2 Open EHI Calls

Open issues are referred to by their call number in the ETAS Helpdesk International (EHI) system.

No EHI calls are open.



3 Change History

3.1 Version 2.0.0

Additional Features

The following features have been added to this release:

- Fully-functional Release
- Support added for untrusted code
- Target option 'Handle FPU context' can be applied to preserve floating point register context during context switches

Modified Features

No features have been modified in this release.

Removed Features

No features have been removed from this release.

3.2 Version 1.99.0

Additional Features

The following features have been added to this release:

- Semi-Functional Preview Release
- Support for the Zhixin Z20K148M, Single Cortex-M4 Core
- Support for the Green Hills Software Compiler v2021.1.4

Modified Features

No features have been modified in this release.

Removed Features

No features have been removed from this release.



4 Fixed EHI Calls

Bugs that have been fixed are referred to by their call number in the ETAS Helpdesk International (EHI) system.

No EHI calls have been fixed in this release.



5 Limitations

5.1 Installer

There are the following limitations for the installer:

Limitation None. **Workaround** None.

5.2 Z20K-M4-GHS DLL

There are the following limitations for this tool:

Limitation Firmware untested on FLASH.

Workaround None.

Limitation The Z20K does not implement the Arm MPU. Instead it uses a SMPU,

which fires a BusFault exception rather than a MemManage exception when a memory access violation happens. As a result, the RTA-OS detects a memory access violation as a BusFault violation. If the user requires the RTA-OS to detect a memory access violation as a MemFault violation, they are required to provide a method of determining the reason for the BusFault exception call. See the

Z20K_M4_GHS Port User Guide for more information.

Workaround None.

Limitation When running code on a Cortex-M4F CPU to avoid the issue de-

scribed in ARM Cortex-M4 Errata 752770 the stack must not be located in Device or Strongly-Ordered memory. For further details

please refer to the ARM Errata documentation

Workaround None.

Limitation According to ARM Errata 838869 when running code on a Cortex-

M4F CPU from memory with a high number of wait states in some circumstances a DSB instruction may be needed at the end of an interrupt handler code. For further details please refer to the ARM

Errata documentation.

Workaround None.



6 Contacting ETAS

6.1 Technical Support

Technical support is available to all users with a valid support contract. If you do not have a valid support contract, please contact your regional sales office (see below).

The best way to get technical support is by email. Any problems or questions about the use of the product should be sent to:

rta.hotline@etas.com

If you prefer to discuss your problem with the technical support team, you call the support hotline on:

+44 (0)1904 562624.

The hotline is available during normal office hours (0900-1730 GMT/BST).

In either case, it is helpful if you can provide technical support with the following information:

- Your support contract number
- The version of the ETAS tools you are using
- The version of the compiler tool chain you are using
- The command line (or reproduction of steps) that result in an error message
- The error messages or return codes you received (if any)
- Your .xml, .arxml and .rtaos files
- The file Diagnostic.dmp if it was generated

6.2 General Enquiries

6.2.1 ETAS Global Headquarters

ETAS GmbH Borsigstrasse 24 Phone: +49 711 3423-0 70469 Stuttgart Fax: +49 711 3423-2106 Germany WWW: www.etas.com

6.2.2 ETAS Local Sales & Support Offices

Contact details for your local sales office and local technical support team (where available) can be found on the ETAS web site:

ETAS subsidiaries www.etas.com/en/contact.php ETAS technical support www.etas.com/en/hotlines.php