MDA V7.2 Hotkey Assignment

General Hints for Use

Ctrl+letter	hold down Ctrl and press the favored letter (key).
Alt+letter	hold down Alt and press the favored letter (key).
Alt+letter, letter	hold down Alt and press the first favored letter (key). Then release Alt and press the second favored letter (key).

Ctrl	Control key
Shift	Shift key
Alt	Alt key
Ins	Insert key
Del	Delete key
Enter	Enter key
Page up, Page down	Page keys

Document V7.2 R01 EN - 03.2016

Measure Data Analyzer

In General	Open the dialog box "Open and Configure"	Ctrl+O
	Save	Ctrl+S
	Zip files	Ctrl+Alt+Z
	Unzip files	Ctrl+Alt+U
	Close	Alt+F4
	Open Variables "All Elements" dialog box	Shift+F4
	Open Configure Windows dialog box	F4
	Open/manage Calculated Signals dialog box	Alt+Q
	Move focus in the tool bar area	Tab
	Activate menu bar	F10
	Move focus to the "from" field	Alt+R
	Move focus to the "to" field	Alt+T
	Toggle window selection	Alt+F6
	Find variable	Crtl+F
	Find configure	Ctrl+Alt+F
	Find next	Shift+Ctrl+F
	Create/edit trigger	Ctrl+T
	Display trigger segments	Ctrl+Shift+F12
Analysis Window	Print dialog	Ctrl+Alt+P
	Next analysis window	Ctrl+F6
	Next analysis window	Ctrl+Tab
	Display information on the selected signal	Ctrl+I
	Show "Align Views" window	Ctrl+Alt+A
	Open/close the "Legend" window	Ctrl+M
	Open "All Elements" dialog box	Ins
	Remove the active signal	Del
	Display information	Alt+Enter
Oscilloscope	Display total measured range	Ctrl+F12
	Toggle the grid display	Alt+G
	Select measure signal	1 … 9 1 … 9
	Select measure signal	10 … 99 Shift+1 … 9 followed by 0 … 9
	Activate legend and signal list alternately	Alt+F6
	Open/close the "Signal List" window	Ctrl+L
	Display measure values physical	Ctrl+P
	Display measure values hexadecimal	Ctrl+H
	Show icons for the signals	Alt+Z
	Reduce value of amplification factor	F6
	Increase value of amplification factor	F7
	Reduce value of base line	Shift+F6
	Increase value of base line	Shift+F7
	Activate the zoom functionality	Ctrl+N
	Undo zooming stepwise	Ctrl+ -Z
	Restore undone zooming steps	Ctrl+Y
	Toggle display mode	Ctrl+R
	Set comment	Ctrl+K
	Toggle the xy-cursor mode	Ctrl+U
Basic Statistics	Export statistic data	Ctrl+E

	Open the statistic settings	Shift+F10, N
Signal List	Move the active signal upwards	Alt+Cursor up
	Move the active signal downwards	Alt+Cursor down
	Open setup	Enter
	Display name settings of the variables	Ctrl+Alt+V
Analysis Cursor	Display cursor	Ctrl+R
	Change active analysis cursor	Ctrl+Q
	Move cursor to the left	Cursor left
	Move cursor to the right	Cursor right
	Move analysis cursor 1	Shift+F11
	Move analysis cursor 2	Shift+F12
Legend/Settings	Toggle edit mode for the selected cell	F2
Zoom Mode	Move the vertical line right (stepwise)	Cursor right
	Move the vertical line left (stepwise)	Cursor left
	Move the vertical line fast to the right	Page up
	Move the vertical line fast to the left	Page down
	Fix the first and the second vertical line: fix the first vertical line at the beginning, the second vertical line at the end of the range, and enlarge the range simultaneously	Enter
Synchronize	Synchronize the views	Ctrl+Alt+S
Configure Windows	Copy selected view and replace signals	Ctrl+Alt+E
Help	Show help file	F1
	Show hot key assignment	Ctrl+F1